•		618	
		CLASSIFICATION SECRETA  SECURITY INFORMATION 25X1	Δ
OUNTRY.	<del>() () () () () () () () () () () () () (</del>	East Germany REPORT NO. 25A II	A
TOPIC		Bremenhain Airfield	
	are a constant		m. 9 * 80 i i
VALUATIO	N	see below PLACE OBTAINED 25X1A	0- XAVA
ATE OF C	ONT	17 June to 11 Contember 1062	
ATE OBTA	NNE		
EFERENC	ES	25X1A	
AGES		ENCLOSURES (NO. & TYPE)	
FMARKS			
	#VE VIII		
a intermedian established the size of	Nome i saliran ess	THE RESERVE OF THE PROPERTY OF	
Veneza	West Tree desired	ANTITION STORM CONTINUENCE TO THE THE STORM CONTINUENCE STORM CONTINUENCE CONT	u tuder
See See to the standard and a	# 0 . <b></b>	The second control of	erna.
OURCE			
		25X1X	
X1X			
		has continued with day and night shifts. In particular, work on the runway has been accelerated. Construction material continuously arrived at the	
	2.	has been accelerated. Construction material continuously arrived at the field.	
	2.	has been accelerated. Construction material continuously arrived at the field.  In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work	
,	2.	has been accelerated. Construction material continuously arrived at the field.  In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premembain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of	
,	2,	has been accelerated. Construction material continuously arrived at the field.  In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau road was completed	
		has been accelerated. Construction material continuously arrived at the field.  In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular textway was to be built and had already been surveyed. However, construction work had not yet started by 11 September.  The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter	
	3.	has been accelerated. Construction material continuously arrived at the field.  In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular textway was to be built and had already been surveyed. However, construction work had not yet started by 11 September.  The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau	
	3.	has been accelerated. Construction material continuously arrived at the field.  In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular textway was to be built and had already been surveyed. However, construction work had not yet started by 11 September.  The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started.  In late August, construction work was completed on five small brick buildings,	
	3. 4.	In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Premenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular textuay was to be built and had already been surveyed. However, construction work had not yet started by 11 September.  The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started.  In late August, construction work was completed on five small brick buildings, allegedly officers billets, near the park of the Bremenhain estate.  A spur track was to be built from the Lodenau-Rothenburg railroad line to the field dump. Three standard-gauge locomotives, one from Hoyerswerda and two from Luckau, were used for construction work.  The concrete mixing installation was still in operation. However, the special tilting cars of Hungarian make were usually under repair. An estimated 700 laborers including 200 to 250 convicts were employed at the	
	3. 4.	In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau read was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular taxiway was to be built and had already been surveyed. However, construction work had not yet started by 11 September.  The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started.  In late August, construction work was completed on five small brick buildings, allegedly officers billets, near the park of the Bremenhain estate.  A spur track was to be built from the Lodenau-Rothenburg railroad line to the field dump. Three standard-gauge locomotives, one from Hoyerswerda and two from Luckau, were used for construction work.	
	3. 4.	In late August 1953, grading work on the landing field was completed. The drainage ditches to be laid at the field are to empty into the Neisse River. Members of the construction staff stated that the location of the airfield was not favorable because of the subsoil water pressure. Concreting work on the section of the runway south of Fremenhain-Lodenau road was completed by 11 September except for a strip in the middle. According to a member of the construction staff, the entire runway was to be completed by 15 October 1953. Allegedly, the runway was to be extended to the north and a circular textway was to be built and had already been surveyed. However, construction work had not yet started by 11 September.  The Lodenau-Noes road was under improvement with the concrete forms having been put in place on one side of the road by 11 September. Concreting work had not yet started. Upon completion of this road, the Bremenhain-Lodenau road will allegedly be demolished. Only after the destruction of the latter road will concreting work on the runway strip north of this road be started.  In late August, construction work was completed on five small brick buildings, allegedly officers billets, near the park of the Bremenhain estate.  A spur track was to be built from the Lodenau-Rothenburg railroad line to the field dump. Three standard-gauge locomotives, one from Hoyerswerda and two from Luckau, were used for construction work.  The concrete mixing installation was still in operation. However, the special tilting cars of Hungarian make were usually under repair. An estimated 700 laborers including 200 to 250 convicts were employed at the field. They worked in two shifts between 3:30 a.m. to 9:30 p.m. The status	

25X1

25X1

25X1

SECRET/

	:		2 <b>-</b> -				25X1A		
	1								
	7.	Since about early Sept by aircraft coming fro Zone of Germany. Alros the zonal border and m aircraft used were pro	m the Polish-oc t every evening ade flights of	cupied German after nightf about 15 minu	territory to	the Soviet t crossed ove	er		
			may was starte	ince late August 1953. Concreting was started on 8 September. uilt in 1954.					
25X1X	9.	Work was under way on line. The trees and te removed and the local approximately in late the railroad line towa	lephone poles s residents expec September. A se	long the Brem ted that the econd spur tra	enhain-Loden road would b ck was being	su road were e blocked			
	10.	Major Mironenko (fnu) in Werder on 31 August a Bauunion conducted a cover which consisted thicker than the top 1 because of the color.	stated that he ork very badly, of two layers o	e was now deta . He showed a of which the b	ched to Roth photograph o ottom layer	enburg where f a concrete was considers	ably		
	11.	On 1 September, source of the runway touched road and kilometer mar strip south of the Bre except for a middle st on a site north of the	both kilometer ker 44.6 of the renhain-Lodenau rip. Four large	marker 47.6 o Bremenhain-I road was com dredgers wer	f the Rothen odenau road. pleted by 1	burg-Bremenha The runway September			
25X1A	1.	Command: The et	atameta en est	atmatian ma	k of Decrease	oin cinfiald			
23/1/	1.4	Comment. The st		istruction wor		Annex to	25X1A		
25X1A		sheet 4655.	For location of	reference po	ints, see Ma	p GSGS 4414,			
25X1A	2.	omment. The ai			ong to the F	ourth Air			
25X1A	7.	Force construction her construction work at I	dquarters in We	erder. Previou	sly, he also				
			en l						
				* * .					
				,					
			•						